Jack Sullivan

From: Pesaturo, Joe [JPesaturo@MBTA.com]

Sent: Friday, April 09, 2010 1:41 PM

To: Jack Sullivan

Cc: Bruce Mohl; Michael Jonas; Robert Sullivan **Subject:** questions about Old Colony tie replacements

Jack-

Please see the T's responses to your questions:

Saw the Ledger e-board story and video and would like the details on the concrete tie replacement, please. I'd like to speak with Rich Davey on this, please, but in the meantime here are some questions: *This is all 145,000 on OCRR plus Boston-Braintree, correct?

That is correct.

*Are they being replaced with wood or concrete?

Wooden ties

*What is the estimated cost and what funds will be used to pay for it, i.e., capital budget, stimulus, general operating?

The MBTA will be soliciting bids for the project next month. The T will award the contract to the qualified and responsive bidder that offers the lowest price. The MBTA will work with MassDOT and its Board of Directors to identify the most suitable funding source (or sources).

*Why, after months of saying the problem is minimal and affects only a small percentage of ties, is the T now replacing the entire batch? Were more problems found? Is the deterioration far more widespread than you initially indicated?

The T had an independent analysis of the ties conducted. The analysts concluded that there was a defect in the make and composition of the concrete ties and that all of them are subject to failure. Therefore, the T has accelerated the program for replacement of the ties.

*Will Rocla be responsible for the entire cost, labor, replacement, shipping, etc., or does their warrnaty just cover product replacement?

The MBTA is seeking full enforcement of its warranty through negotiations, if possible, or through litigation if necessary. Negotiations continue at this stage in the process. The scope of the warranty is among the issues being discussed between the parties.

From: Jack Sullivan [mailto:jsullivan@MassINC.org]

Sent: Friday, April 09, 2010 10:41 AM

To: Pesaturo, Joe

Subject:

Joe

Saw the Ledger e-board story and video and would like the details on the concrete tie replacement, please. I'd like to speak with Rich Davey on this, please, but in the meantime here are some questions: *This is all 145,000 on OCRR plus Boston-Braintree, correct?

*Are they being replaced with wood or concrete?

*What is the estimated cost and what funds will be used to pay for it, i.e., capital budget, stimulus, general operating?

*Why, after months of saying the problem is minimal and affects only a small percentage of ties, is the T now replacing the entire batch? Were more problems found? Is the deterioration far more widespread than you initially indicated?

*Will Rocla be responsible for the entire cost, labor, replacement, shipping, etc., or does their warrnaty just cover product replacement?

*Is the T planning on taking them to court or has a settlement been reached?

I'm sure I'll have more questions.

Jack Sullivan Senior Investigative Reporter CommonWealth magazine 18 Tremont St., Ste 1120 Boston, MA 02108 jsullivan@massinc.org

This email has been scanned by the MessageLabs Email Security System on behalf of the MBTA ITD Department and has been found to contain no viruses.

Please consider the environment before printing this e-mail.

This email/electronic message, including any attached files, is being sent by the MBTA. It is solely intended for the recipient(s) and may contain information that is proprietary, confidential, legally privileged, and/or exempt from disclosure pursuant to state and federal law. If you have received this message in error or are not the intended recipient(s), please notify the sender immediately by reply, and delete all copies of this email/electronic message and any attached files from your computer. If you are the intended recipient(s), you may use the information contained in this email/electronic message and any attached files only as authorized by the MBTA. Any unauthorized use, dissemination, or disclosure of this email/electronic message and/or its attached files is strictly prohibited.

Please consider the environment before printing this e-mail.